



Care and Maintenance

Composite/Fiberglass

Remove ordinary dirt and smudges with a mild dish soap and warm water solution. Rinse with a water dampened cloth. Dry with a clean soft cloth. Heavy soiling can be removed with mild non-abrasive household cleaners and a soft cloth.

T-Mold and SPACEdge

Use a liquid detergent suitable for cleaning vinyl or mild liquid detergent. After cleaning, wipe the surface with a cloth dampened with warm water. Wipe dry with a soft cloth.

Laminate

To remove stains, wipe the surface with a damp cloth using a mild liquid detergent. Remove stubborn stains with a damp paste of baking soda. Leave on for a minute and then blot away. Do not use abrasive cleaners. Acid based products spilled on the surface should be wiped off immediately and then rinsed.

Wood Tops/Wood Edge

Gently clean with a soft cloth dampened with a mild detergent and water solution. Wipe dry with a clean soft cloth. Scratches in the wood can be repaired using a colored wax repair stick. Liquid spill should be wiped dry immediately. Do not use ammonia, bleach, degreasers or abrasive cleaners.

3D Laminate

Wipe with a damp cloth and mild dish soap and warm water. Dry with a clean soft cloth. Avoid any cleaners with ammonia or baking soda. Disinfecting – A mixture of 10% bleach, 90% water can be used as a disinfectant on most thermofoil surfaces. Test on non-visible spot before using.