

Care and Maintenance

Laminate Table Tops w/ Wood Edge

Gently cleanse with a soft cloth dampened with mild detergent and water solution. Wipe dry with a clean soft cloth. Scratches in the wood can be repaired using a colored wax repair stick.

Spills of liquid should be wiped dry immediately. Do not use ammonia, bleach, degreasers or abrasive cleaners. Avoid prolonged or excessive exposure to direct sunlight, high temperature or high or low humidity. Improper care will void the manufacturer's warranty.

Laminate Table Tops w/ Tmold or SPACEdge

Use a clean, damp, non-abrasive cotton cloth and a mild liquid detergent or household cleaner. Rinse with clean water, using a clean, non-abrasive cotton cloth. Do not flood the laminate, especially near seams, since water can penetrate and cause the substrate to swell. Dry the surface with a soft, clean, non-abrasive cotton cloth.

Matte and Sparkle Finishes. Especially hard to clean areas may require special attention. Use a nylon bristle hand or vegetable brush along with a mild liquid detergent and water solution. Rinse and dry thoroughly.

High Gloss Finishes. If residual streaks and smears remain after normal cleaning, use a mild glass cleaner and then dry with a clean, non-abrasive cotton cloth. Avoid exterior glass cleaners.

*On all laminate finishes, NEVER use cleaners containing acid, alkali, or sodium hypochlorite. These cleaners will mar, etch, corrode and permanently discolor the surface and void manufacturer's warranty.

**Stains. To remove or minimize stains, use full strength Fantastik All Purpose Cleaner, Formula 409, Pine-Sol (original formulation) or other mild household cleaner and allow it to draw out the stain. Blot with clean, damp, non-abrasive cotton cloth, rinse with clean water and dry thoroughly.

3D Laminate Table Tops

Wipe with a damp cloth or sponge with mild dish soap, or wipe with a damp cloth or sponge using a 50/50 mix of water and Simple Green. (Simple Green works well on oily or tacky surfaces. Avoid any cleaners with ammonia or baking soda.

Stains. Step 1 – Using a damp cloth with a 50/50 mix of water and simple green, scrub lightly for 10 to 20 strokes.

Persistent stains. Step 2 - Using a damp cloth or sponge with Buckeye Workout, standard Fantastik, or standard Formula 409. Lightly stroke for 10 – 20 strokes. If stain persists, Step 3 – Place a cloth or sponge damp with 70% Isopropyl Alcohol on top of the stain for 30 minutes. After 30 minutes, remove the cloth or sponge and wipe.

Disinfecting – A mixture of 10% bleach, 90% water can be used as a disinfectant on most thermofoil surfaces. Before using, test on a non-visible spot.

Composite (Fiberglass) Table Top Cleaning

Wash with a mixture of mild detergent and warm water and a non-abrasive cloth (a brush may be used-test a small area first for scratching). For a very soiled top use a mixture of Soilax and warm water. Rinse with water and dry.